

FIG. 1F




FIG. 1H




FIG. 1I




FIG. 2




FIG. 3

864F50442652060




FIG. 5




FIG. 4




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D




FIG. 4E




FIG. 4F




FIG. 4G




FIG. 4H




FIG. 4I




FIG. 4J






FIG. 4K






Fig 6b




Fig 6c

return spring 90






FIG. 6E







FIG
6g

alternates
mounting
with bushings

FIG 7



28

move

blowing on
filter paper
fig




Fig 4g - 13 -

Fig 4g

immersed
for 1000 hrs

done




FIG. 7C




FIG. 7B





FIG. 7A

FIG 7D






FIG. 8




FIG. 9





FIG. 10






FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17A

FIG. 17B

FIG. 17C

FIG. 17D




FIG. 18A

FIG. 18B

FIG. 18C

FIG. 18D




FIG. 19A

FIG. 19B

FIG. 19C

FIG. 19D